





Disintegration of Luminaire into part for Maintance of

- End Cap Grab screw Remove - End Cap Remove - Insert Removal From Below - Remove Wire Connection - Wire Connection Indriver - Put Insert Back Into Outer Profile - End Cap Grab screw Remove - End Cap Remove Insert Removal From Below
Remove Connect Wire From Wago connector
Unscrew Lens With PCB - Add New PCB with heat tap on back side - Connection Again - Put Lens With PCB Back - Put Insert into Outer Profile

2

В

F

E

D

С





